


# FIG. 1


(EXAMPLE 1) CONTINUOUS PHASE (RUBBER COMPONENT: DARK REGION) /  
DISCONTINUOUS PHASE (RESIN COMPONENT: LIGET REGION)



× 10,000


## FIG.2

(EXAMPLE 2) CONTINUOUS PHASE (RUBBER COMPONENT: DARK REGION) /  
DISCONTINUOUS PHASE (RESIN COMPONENT: LIGET REGION)



## FIG.3

(EXAMPLE 3) CONTINUOUS PHASE (RESIN COMPONENT: LIGET REGION) /  
DISCONTINUOUS PHASE (RUBBER COMPONENT: DARK REGION)



× 10,000

## FIG.4

(EXAMPLE 4) CONTINUOUS PHASE (RESIN COMPONENT: LIGET REGION) /  
DISCONTINUOUS PHASE (RUBBER COMPONENT: DARK REGION)

